

KIRK WIRELESS SERVER 600V3 WHEN RUNNING CISCO SKINNY PROTOCOL

SERVICE NEWS 149

CONCERNING:

KIRK Wireless Server 600v3 when running CISCO Skinny Protocol

INFORMATION:

New IP Firmware 60600-07 and Radio Firmware PCS04db

- IP file Name: 07-60600-07.bin
- Radio File Name: PCS04Db.bin

Added compatibility:

CCM version 5.1

CCME version 4.0.

Features added:

IP:

- Login/Logout hunting groups
- Call Park/Retrieve on CCME

BMC:

- PP Clock update at location registration implemented

Corrected bugs:

IP:

- Memory leak
- LDAP problem

BMC:

- SyncMaster will now not go into sync with RPN 0
- Memory leak

Corrected ID bugs:

- ID-01749-02ZZCS
- ID-01733-LZS9ZJ

Actions before upgrade:

- Go to www.kirktelecom.com/Installer/suk227.asp and download the software to your PC or PC Network.
- Backup all KIRK Wireless Server 600v3 configuration files before the update is performed.

Actions during upgrade:

- Recommendation is to do the update on-site.
- Update the IP Firmware.
- Update the BMC SW.
- Restart the system.

Actions after upgrade:

- Make a complete test of the system and connected handsets.
- If you have an open ID Case, please test that your problem has been solved. Please do not forget, to report back to KIRK telecom, that the problem has been solved.

Note:

- Please keep in mind that IP Firmware 60600-07 and BMC Version PCS04Db will not be working together with older released Firmware or BMC SW. Therefore, as soon as the update is started, both SW types must be updated before the unit will work again.
- All KIRK Wireless Server 600v3 units in the same multi-cell solution must be updated.
- Update time for each unit will take approximately 5 minutes.
- System downtime will be approximately 1-3 hours depending on system size.