



KIRK Release Note
KIRK 5040

Firmware Version PCS 07Hb
Q2/2009

Table of Contents

1. INTRODUCTION.....	1
2. GENERAL.....	1
3. IMPORTANT NOTES.....	1
4. DISTRIBUTION FILES	1
5. CHANGES.....	1
5.1 VERSION PCS 07HB (Q2/2009).....	1
5.1.1 <i>Added or Changed Features</i>	1
5.1.2 <i>Removed Features</i>	1
5.1.3 <i>Corrections</i>	1
6. CONFIGURATION FILE PARAMETER CHANGES.....	1
6.1 VERSION PCS 07AA (Q1/2009).....	1
6.1.1 <i>Added or Changed Features</i>	1
6.1.2 <i>Removed Features</i>	2
6.1.3 <i>Corrections</i>	2
7. CONFIGURATION FILE PARAMETER CHANGES.....	2

1. Introduction

2. General

This release note applies to firmware PCS 07Hb of the KIRK 5040. This release is a main release that replaces the PCS 07Aa release as the latest generally available (GA) release.

3. Important Notes

Please note that this release note and its firmware upgrade only apply for the KIRK 5040. For the KIRK 5020, please refer to KIRK 5020 Release Note Q2/2009.

4. Distribution Files

Please click [here](#) to download the firmware PCS 07Hb

5. Changes

5.1 *Version PCS 07Hb (Q2/2009)*

5.1.1 Added or Changed Features

- The handset will automatically upgrade the Bluetooth firmware.

5.1.2 Removed Features

None.

5.1.3 Corrections

- Excessive messaging could cause the handset to restart or turn off. Problem fixed by optimizing heap usage.
- Time when returning from out of range back into range, improved from 10 to 3 seconds.

6. Configuration File Parameter Changes

- None.

6.1 *Version PCS 07Aa (Q1/2009)*

6.1.1 Added or Changed Features

- Added locally generated Call Progress Tones (CPT) for Australia and United Kingdom (relevant for the KWS300 and KWS6000 solutions). From the HMP the following country specific CPT can be selected:
 - Denmark

- United States
 - United Kingdom
 - Australia
 - Germany
-
- When the keyboard is locked, a small lock icon is shown in the info bar at the top of the display instead of a big lock icon at the screen center.
 - Via the HMP it is possible to personalize the standby logo of the handset.
 - Ringer tone 5 has been replaced by the sound of an analog phone
 - Ringer tone 6 has been replaced by ringer tone 6 from the KIRK 40xx (high volume with high frequency tones).

6.1.2 Removed Features

None.

6.1.3 Corrections

- Pressing the R-key when receiving a message during conversation would terminate the call. The message is now exited and the phone returns to the call display.
- Subscribed to a KWS600v3 system, the handset did not distinguish between internal and external incoming calls. This has now been corrected.
- Subscribed to a KWS300 or KWS6000 system, the volume of the dial tone could not be changed. This has now been corrected.
- Subscribed to a residential system, entering a number and pressing the R-key would make an internal handset to call. Now only a one digit number can be called. If entering more than one digit and pressing the R-key, the phone returns to idle.
- Subscribed to a KWS300 or KWS6000 system, CPT could not be heard in the wireless headset. This has now been corrected.

7. Configuration File Parameter Changes

None.