



*KIRK Release Note*  
*KIRK 5040*

**Firmware Version PCS 07Aa**  
Q1/2009



## Table of Contents

<b>1. INTRODUCTION.....</b>	<b>1</b>
1.1 TERMS AND DEFINITIONS.....	1
<b>2. GENERAL.....</b>	<b>1</b>
<b>3. IMPORTANT NOTES.....</b>	<b>1</b>
<b>4. DISTRIBUTION FILES .....</b>	<b>1</b>
<b>5. CHANGES.....</b>	<b>1</b>
5.1 VERSION PCS 07AA (Q1/2009).....	1
5.1.1 <i>Added or Changed Features</i> .....	1
5.1.2 <i>Removed Features</i> .....	2
5.1.3 <i>Corrections</i> .....	2
<b>6. CONFIGURATION FILE PARAMETER CHANGES.....</b>	<b>2</b>



## 1. Introduction

### 1.1 Terms and Definitions

CPT            Call Progress Tones

HMP            Handset Management Program 50xx version 1.3.0.18 or later

## 2. General

This release note applies to firmware PCS 07Aa of the KIRK 5040.

This release is a main release that replaces the PCS 06Ma release as the latest generally available (GA) release.

## 3. Important Notes

Please note that this release note and its firmware upgrade only apply for the KIRK 5040. For the KIRK 5020, please refer to KIRK 5020 Release Note Q1/2009.

## 4. Distribution Files

Contact Kristian Ehrenreich for the firmware image PCS 07Aa of the KIRK 5040 platform at [kristian.ehrenreich@polycom.com](mailto:kristian.ehrenreich@polycom.com)

## 5. Changes

### 5.1 Version PCS 07Aa (Q1/2009)

#### 5.1.1 Added or Changed Features

- Added locally generated Call Progress Tones (CPT) for Australia and United Kingdom (relevant for the KWS300 and KWS6000 solutions). From the HMP the following country specific CPT can be selected:
  - Denmark
  - United States
  - United Kingdom
  - Australia
  - Germany
  
- When the keyboard is locked, a small lock icon is shown in the info bar at the top of the display instead of a big lock icon at the screen center.
- Via the HMP it is possible to personalize the standby logo of the handset.
- Ringer tone 5 has been replaced by the sound of an analog phone

- Ringer tone 6 has been replaced by ringer tone 6 from the KIRK 40xx (high volume with high frequency tones).

### **5.1.2 Removed Features**

None.

### **5.1.3 Corrections**

- Pressing the R-key when receiving a message during conversation would terminate the call. The message is now exited and the phone returns to the call display.
- Subscribed to a KWS600v3 system, the handset did not distinguish between internal and external incoming calls. This has now been corrected.
- Subscribed to a KWS300 or KWS6000 system, the volume of the dial tone could not be changed. This has now been corrected.
- Subscribed to a residential system, entering a number and pressing the R-key would make an internal handset to call. Now only a one digit number can be called. If entering more than one digit and pressing the R-key, the phone returns to idle.
- Subscribed to a KWS300 or KWS6000 system, CPT could not be heard in the wireless headset. This has now been corrected.

## **6. Configuration File Parameter Changes**

None.