

KIRK SYSTEM 500

SERVICE NEWS 074

Release of New flash-software for KIRK System 500

CONCERNING:

New software version 1N for KIRK System 500

REASON:

Software version 1N has been developed to cure the problem referred to in Service News No. 69 & 71.

CORRECTIVE ACTION:

Upload of new software version 1N.
Re. Service News No. 52.

BE AWARE:

If upgrading from 1G to 1M please refer to Service News No. 55.


REMARK:

The software-reset function is disabled in the software version 1N.
In situations where the CCFP Adm. Program is expecting a software reset e.g. after "Clear EEPROM", "Restore Data to CCFP" and "Restart System" a restart of the CCFP Adm. Program is necessary.
The system 500 must be reset by a power-reset in the above mentioned situations as well - Power Off/On.

Restore EEPROM Data to CCFP

Clear EEPROM

Restart System



Systems manufactured from week 06 - 2003 will be delivered with software version 1N.

The software version 1N can be here