

SERVICETOOL

SERVICE NEWS 141

CONCERNING:

ServiceTool.

INFORMATION:

New version of the program ServiceTool - version 4.18.

New implementation:

- Text in general changed matching new terms after the introduction of KWS600v3 and 4ch. repeaters.
- Method II regarding Load of Flash to handset is removed.
- Help section in general improved.

Please refer to the HELP file in the ServiceTool for further information concerning changes implemented.
Can be found under folder - Facilities implemented & bugs corrected.

Please go to: www.kirktelecom.com/Installer/suk205.asp for download of this version.