



POLYCOM®

Release Notes

3Com
SoundStation® IP
Version 1.6R

22 November 2004

Table of Contents

1. GENERAL	1
2. UPGRADE	1
3. CAVEATS	1
3.1 OPEN	1
3.2 CLOSED	1
4. OTHER KNOWN PROBLEMS	1

1. General

These release notes apply to version 1.6R of the 3Com SoundStation IP application.

2. Upgrade

Normal upgrade from all versions.

3. Caveats

3.1 Open

- 3862: **PRB02381 - VLAN Control is not working for Polycom**
- 3863: **PRB02382 - Vlan Download functionality is req'd for Polycom**
- 3864: **PRB02343 - IP Polycom Drops Calls intermittently**
- 3865: **PRB01407 - 3rd party Polycom SSIP is being instructed to use scrambled audio**
- 3866: **PRB01419 - Polycom SSIP doesn't correctly rejoin a confr. after reboot**

3.2 Closed

The following issues have been resolved with this release:

- 7208: **Cannot set subnet mask statically or from NBX**

4. Other Known Problems

- 9426: **SSIP got corrupted during upgrade attempt**

- **9427: Writing to flash failed**

The phone may fail to upgrade. The phone will no longer be functional.

Workaround: None

- **9336: SoundStation 3Com froze while it was waiting for the NCP to respond**

Workaround: Power cycle the phone

- **9403: Layer 2 SSIP loses audio on conference call**

Workaround: Power cycle the phone