



POLYCOM®

KIRK Release Note

KIRK WRFP12 REPEATER

Firmware Version PCS23__

Table of Contents

1. GENERAL	1
2. REFERENCES	1
2.1 IMPORTANT NOTES	1
2.2 FEATURE LICENSE AND PLATFORM LIMITATIONS	1
2.3 SYSTEM REQUIREMENTS	1
3. TERMS AND DEFINITIONS	1
4. DISTRIBUTION FILE	1
5. CHANGES	1
5.1 VERSION PCS01AD	1
6. OUTSTANDING ISSUES	1

1. General

This release note applies to the released versions of the KIRK WRF12 repeater firmware. This version specifically applies to version PCS23__ of the KIRK WRF12 repeater. release.

2. References

None.

2.1 Important Notes

None.

2.2 Feature License and Platform Limitations

None.

2.3 System Requirements

Hardware Platform:	Description
KIRK repeater 14182400 HW PCS 3 or newer	KIRK WRF12 repeater

3. Terms and Definitions

None.

4. Distribution File

K:\PH\141204XX\00\HEX\PIE23__\14120400_023__.hsx

5. Changes

5.1 Version PCS23__

Because of known problems in version PCS24__ we downgrade to version PCS23__ until a solution has passed qualification test..

6. Outstanding Issues

The following issues will be fixed in a subsequent release

- China, South America and US frequencys to bee added.
- Adaption to Peltor P840 system

