



POLYCOM®

*KIRK Release Note*  
KIRK® Wireless Server

Firmware Version **V8.00 hotfix7 10-80500.27**  
and **PCS05Ag**  
and boot code **10-8050027**  
Q2, 2011



## Table of Contents

<b>1. REVISION HISTORY .....</b>	<b>1</b>
<b>2. GENERAL.....</b>	<b>2</b>
2.1 TERMS AND DEFINITIONS.....	2
2.2 RELEASE .....	2
2.3 TARGET GROUP .....	2
2.4 IMPORTANT NOTES .....	2
2.5 FEATURE LICENSE AND PLATFORM LIMITATIONS .....	2
2.6 SYSTEM REQUIREMENTS.....	2
<b>3. DISTRIBUTION FILES .....</b>	<b>3</b>
<b>4. CHANGES.....</b>	<b>3</b>
4.1 VERSIONS V8.00 HOTFIX7 10-80500.27 AND PCS05AG AND BOOT CODE 10-8050027 – Q2, 2011	3
<b>5. OUTSTANDING ISSUES.....</b>	<b>3</b>



## 1. Revision History

Initials	Date	Version	Description
Kjl	2010-03-08	1	Release notes for ip firmware: V8.00 hotfix7 10-805000.27 and radio: PCS05Ag. <b>For SIP only.</b>

## 2. General

### 2.1 Terms and Definitions

None

### 2.2 Release

This release note applies to the released versions of the KIRK Wireless Server 600v3 firmware. This version specifically applies to versions V8.00 hotfix7 10-80500.27 and PCS05Ag and boot code 10-8050027 of the KWS600v3 firmware. The release is the latest generally available (GA) release.

### 2.3 Target Group

- Polycom product management
- Polycom service and support
- Polycom R&D

### 2.4 Important Notes

This firmware release has been tested on our automatic system against the following systems:

- Digium Asterisk
- CUCM 8.0.2 SIP Setup
- Broadsoft
- Mitel

Besides the system test our msf interface has been tested with our automatic system and our msf stress tester.

If you are upgrading from a v6 official release, you have to make use of the upgrade kit:

Click [here >>](#) to download the KWS600v3 ServiceReleaseUpgradeKit.

If you are upgrading from a v7 hotfix release, you can follow the procedures described in the KWS600v3 upgrade guide.

Upgrade all units on the system with the new firmware files.

### 2.5 Feature License and Platform Limitations

None

### 2.6 System Requirements

Hardware Platform:	Description
KWS600v3	KIRK Wireless Server 600v3

### 3. Distribution Files

Click [here >>](#) to find and download the following files:

Files	Description
Q1\KIRK_KWS600v3_ServiceReleaseUpgradeKit	Upgrade kit to use when updating from v6 releases
ip1200.bin	V8 ip firmware: 10-80500.27
boot1200.bin	V8 bootcode: 10-8050027
fp_1g8_ip_1200.bin	New radio firmware: PCS05Ag
relnotes.txt	Readme file describing changes in v8

### 4. Changes

#### ***4.1 Versions V8.00 hotfix7 10-80500.27 and PCS05Ag and boot code 10-8050027 – Q2, 2011***

This upgrade is an update to a whole new branch. To see the changes, refer to the readme.txt file (see Distribution files above).

### 5. Outstanding Issues

For details about the test results listed below, please send an e-mail to [mette.phillips@polycom.com](mailto:mette.phillips@polycom.com).

- Asterisk single cell test result  
**Failed test cases:** 5.5; 9.2; 9.7; 13.4; 13.5; 13.6; 13.7; 13.8; 13.9
- Asterisk multi cell test result  
**Failed test cases:** 5.5; 13.4; 13.5; 13.6; 13.7; 13.8; 13.9
- Broadsoft single cell test result  
**Failed test cases:** 5.5; 9.2; 9.7; 13.4; 13.5; 13.6; 13.7; 13.8; 13.9
- Broadsoft multi cell test result  
**Failed test cases:** 5.5; 13.1; 13.4; 13.5; 13.6; 13.7; 13.8; 13.9
- Cisco single cell test result  
**Failed test cases:** 5.5; 9.2; 9.7; 13.4; 13.5; 13.6; 13.7; 13.8; 13.9