

KIRK WIRELESS SERVER 1500

Service News 124

CONCERNING:

New software for - KIRK Wireless Server 1500

File name: 13300110_PCS_05C_.ktb

New software has been released for KIRK Wireless Server 1500.

INFORMATION:

Misdialling numbers:

It has in some case been found that handsets used on KWS 1500 are dialling wrong numbers. A Slow dial function is now implemented in the software PCS 5C_ to prevent this phenomenon.

Daily restart:

An opportunity for a daily restart function is implemented.

Future feature:

Prepared for the new release of handset software for KIRK 40XX - new facilities.

Units delivered from week 38 - year 2005 will be equipped with this version.