

## **Cumulative Release Notes**

### **6020 Administration Tool (HandsetAdmin.exe)**

#### **1.01.07**

- Fixed a problem that occasionally caused the Administration Tool to crash when the handset in the USB cradle did not have a battery inserted.
- Released with an updated version of the USB drivers which are compatible with Windows 2000

#### **1.01.06 (limited release)**

- A number of cosmetic and user interface changes
- Improved application stability
- This version is compatible with the mechanism used in the handset software to prevent loading incompatible software in the handset. Required for most handsets shipped with handset software version 110.011 and later.

#### **1.00.01**

- Initial software release
- Initial drivers release