



KIRK[®] Release Note
KIRK Base Station

Firmware Version PCS03D_
Q1/2010

Table of Contents

1. GENERAL	1
2. REFERENCES	1
2.1 IMPORTANT NOTES	1
2.2 FEATURE LICENSE AND PLATFORM LIMITATIONS	1
2.3 SYSTEM REQUIREMENTS	1
3. TERMS AND DEFINITIONS	1
4. DISTRIBUTION FILE	1
5. CHANGES	1
5.1 VERSION PCS03D_ Q1, 2010	1
5.1.1 <i>Added or Changed Features</i>	1
5.1.2 <i>Removed Features</i>	1
5.1.3 <i>Corrections</i>	1
5.1.4 <i>Configuration Parameter Changes</i>	2
5.2 VERSION PCS03C_ Q4 2009	2
5.2.1 <i>Added or Changed Features</i>	2
5.2.2 <i>Removed Features</i>	2
5.2.3 <i>Corrections</i>	2
5.2.4 <i>Configuration Parameter Changes</i>	2
5.3 VERSION PCS03B_.....	2
6. OUTSTANDING ISSUES	2

1. General

This release note applies to the released versions of the KIRK Base Station firmware. This version specifically applies to version PCS03D_ of the KIRK Base Station. This release replaces the PCS03C_ release as the latest generally available (GA) release.

2. References

None.

2.1 Important Notes

None

2.2 Feature License and Platform Limitations

None.

2.3 System Requirements

Hardware Platform:	Description
KIRK Base Station 14170000 HW PCS 4 or newer	KIRK RFP Base Station

3. Terms and Definitions

None.

4. Distribution File

Please click [here >>](#) to find firmware image PCS03D_ of the KIRK Base Station.

5. Changes

5.1 Version PCS03D_ Q1, 2010

5.1.1 Added or Changed Features

- Mail trace added.

5.1.2 Removed Features

None

5.1.3 Corrections

- Stable Q value at slot 1. Mail trace added.

5.1.4 Configuration Parameter Changes

When upgrading from PCS 03Ap to PCS 03D_ the base station requires a soft default.

5.2 Version PCS03C_ Q4 2009

5.2.1 Added or Changed Features

- Cipherring enabled.
- RSSI scanning and scanning after other bases added.
- Serial command read and set even/odd slot in EEPROM.
- Serial command read and set RFcarriers available in EEPROM.
- Serial command read and set priority (Bosch) bit in EEPROM.

5.2.2 Removed Features

None

5.2.3 Corrections

- Bug changing dummy bearer to same slot fixed.
- Bug in antenna diversity fixed.

5.2.4 Configuration Parameter Changes

None

5.3 Version PCS03B_

Initial KIRK RFP5 Base Station release.

6. Outstanding Issues

The following issues will be fixed in a subsequent release

- None identified.