

## **SRP Gateway External Release Notes (32.116) – 24 September 2009**

This is a release load. It is based on release load 32.115.

### ***Versions***

Functional Code      32.116            tgx150a.bin

### ***New Features***

- Add OAI Graphics support to SRP (Netlink) Gateway

### ***Fixes***

- WINF-91 Svc Esc (437290): No audio path when connecting through OAI to patient room
- WINF-105 Set multiline display from Txt Msg app sent immed. after ring is blank screen almost every time
- WINF-130 Add OAI Graphics support to SRP (Netlink) Gateway

### ***Known Issues (bugs)***

- None